

B. M. ROSS AND ASSOCIATES LIMITED
Engineers and Planners
62 North Street, Goderich, ON N7A 2T4
p. (519) 524-2641 www.bmross.net

File No. 81017C

VIA EMAIL ONLY

April 13, 2022

Ian Mitchell, District Engineer
Ministry of the Environment, Conservation and Parks
Owen Sound District Office
101 17th Street East, Third Floor
Owen Sound, ON N4K 0A5

RE: Stephen Landfill (Closed) Status Report (2020-2021)
Certificate of Approval No. A162102

On behalf of the Municipality of South Huron, please find enclosed the 2020-2021 annual report for the Stephen Landfill (Closed), as follows:

- An electronic copy of the “Stephen Landfill Status Report (2020-2021) Volume I – Report” and “Stephen Landfill Status Report (2020-2021) Volume II – Figures & Appendices”, both dated April 13, 2022.
- An electronic copy of the completed Monitoring and Screening Checklist.


As noted in Section 3.3 b), SP2-93 was destroyed in 2016 (likely by adjacent agricultural activities). The Municipality is proposing not to reconstruct SP2-93 and is requesting that it be removed from the approved monitoring program. In addition, the Municipality is requesting to formally abandon OW17-3 and OW18-3, due to the sale of the property north of the landfill, and remove them from the current monitoring program.

Additional reasons for the above request are detailed within the report.

If you have any questions, please contact us.

Yours very truly,

B. M. ROSS AND ASSOCIATES LIMITED

Per 
Ryan DeVries, P. Eng.

RPD:es
Encl.

c.c. Don Giberson, Municipality of South Huron